

Audi
Service record



Complete record

Vehicle data

Vehicle identification number	WAUZZZ4G2JN100143
Type designation	A6 Sal. TDI2.0 I4140 A7
Date of delivery	

Delivery inspection

Date	2018-07-03
Mileage/km	0 km
Order number	WAUZZZ4G2JN100143
Carried out by	NVD Balldonnell D22 Dublin Ireland
Authorised Audi dealer	Yes



PRO-FORMA INVOICE

Invoice Name & Address
Mr Jonathan O'Connor Abbeyview Lodge, Mourneabbey Mallow Co. Cork

Customer Name & Address
Mr Jonathan O'Connor Abbeyview Lodge, Mourneabbey Mallow Co. Cork

You were served by: Philomena Radcliffe Operator: PR

Account No.	Document Number	Date & Tax Point	Repair Date	Order Number	
C0002	0	09/01/2020			
Make & Model	Chassis No.	Engine No.	Mileage	Time	Page
A6 2.0TDI 190 S LINE S-T 20	WAUZZZ4G2JN100143	DDD059030	43777	12:23	1
Next Service Date	Service due at	Reg No.	Reg Date.	VSF No.	W.I.P. No.
31/12/2019	16765	182D6758	06/07/201		W 46879

	Description of Goods / Services	Qty.	Unit Price	Unit Des.	Net Total	V
A	AVS2 Carried out 2nd Audi variable Service Replace Oil, Oil filter and Pollen Filter. Replace Fuel filter on Diesel models. Carry out EVHC checking Brakes, Tyres, Suspension, Engine and Gearbox components visually and report findings.				212.50	L
X	Z99A Environmental Waste	4	3.47	EACH 0.00	13.88	L
X	Z99B Consumables	4	2.75	EACH 0.00	11.00	L
X	Z500 Castrol Edge Profess	10	6.75	EACH 0.00	67.50	L
X	AG 052164M2 SCREEN WASH WINTER	1	4.01	EACH 14.0	3.45	L
X	AN 90813202 SUMP BUNG	1	3.21	EACH 35.0	2.09	L
X	A03N115562B FILTERELEM	1	11.80	EACH 35.0	7.67	L
X	A4H0819439 POLLEN FILTER	1	49.73	EACH 35.0	32.33	L
X	A4G0127401 FUEL FILTER	1	36.40	EACH 34.0	24.03	L
				Sub-Total (Ex VAT)	374.45	
				Vat Inc.	425.00	
T	COMP Complimentary 12 Month Audi Assist Breakdown 1800 202 103 Complimentary wash & vacuum				0.00	L
				Sub-Total (Ex VAT)	0.00	
				Vat Inc.	0.00	
T	NEXT				0.00	L

E. & O. E.

Address Dublin Road
Castletroy
Co. Limerick
Telephone 353 61 336000
Fax 353 61 330024
e-mail info@audilimerick.ie
Internet www.audilimerick.ie

Registered Office Joe Duffy (Motors) Ltd
Exit 5, M50
Northroad
Dublin 11
Ireland 550383
Registered in
VAT No. 3288047QH



PRO-FORMA INVOICE

Invoice Name & Address
Mr Jonathan O'Connor Abbeyview Lodge, Mourneabbey Mallow Co. Cork

Customer Name & Address
Mr Jonathan O'Connor Abbeyview Lodge, Mourneabbey Mallow Co. Cork

You were served by: Philomena Radcliffe Operator: PR

Account No.	Document Number	Date & Tax Point	Repair Date	Order Number		
C0002	0	09/01/2020				
Make & Model	Chassis No.	Engine No.	Mileage	Time	Page	
A6 2.0TDI 190 S LINE S-T 20	WAUZZZ4G2JN100143	DDD059030	43777	12:23	2	
Next Service Date	Service due at	Reg No.	Reg Date.	VSF No.	W.I.P. No.	
31/12/2019	16765	182D6758	06/07/201		W 46879	

	Description of Goods / Services	Qty.	Unit Price	Unit Des.	Net Total	V
	Next Service Due @ 73,777 kms or on 09/01/2022			Sub-Total (Ex VAT) Vat Inc.	0.00 0.00	
T	2013A Our Factory Trained Technician has carried out a Visual Health Check on your Audi vehicle today. This check is Free of Charge Please see your report below:			Sub-Total (Ex VAT) Vat Inc.	0.00 0.00	L
T	2014 BRAKE WEAR REPORT - Percentage of worn % FRONT PADS 50% DISCS 38% REAR PADS 35% DISCS 25%			Sub-Total (Ex VAT) Vat Inc.	0.00 0.00	L
T	2016 TYRE WEAR REPORT MM - Remaining on Tyre L/H/F 3mm - R/H/F 3mm L/H/R 6.5mm - R/H/R 6mm Bad Sidewall Damage to Front Left Tyre				0.00	L

V	Rate	Service/Goods	V.A.T.

Address Dublin Road
Castletroy
Co. Limerick
Telephone 353 61 336000
Fax 353 61 330024
e-mail info@audilimerick.ie
Internet www.audilimerick.ie

Registered Office Joe Duffy (Motors) Ltd
Exit 5, M50
Northroad
Dublin 11
Registered in Ireland 550383
VAT No. 3288047QH



PRO-FORMA INVOICE

Invoice Name & Address
Mr Jonathan O'Connor Abbeyview Lodge, Mourneabbey Mallow Co. Cork

Customer Name & Address
Mr Jonathan O'Connor Abbeyview Lodge, Mourneabbey Mallow Co. Cork

You were served by: Philomena Radcliffe Operator: PR

Account No.	Document Number	Date & Tax Point	Repair Date	Order Number	
C0002	0	09/01/2020			
Make & Model	Chassis No.	Engine No.	Mileage	Time	Page
A6 2.0TDI 190 S LINE S-T 20	WAUZZZ4G2JN100143	DDD059030	43777	12:23	3
Next Service Date	Service due at	Reg No.	Reg Date.	VSB No.	W.I.P. No.
31/12/2019	16765	182D6758	06/07/201		W 46879

	Description of Goods / Services	Qty.	Unit Price	Unit Des.	Net Total	V
	Legal Limit is 1.6mm					
				Sub-Total (Ex VAT)	0.00	
				Vat Inc.	0.00	

E. & O. E.			V	Rate	Service/Goods	V.A.T.		
Parts	137.07		L	13.50	374.45	50.55	Net	374.45
Surcharge	0.00						V.A.T.	50.55
Labour	212.50						Total	425.00
Sublet	0.00						Paid	0.00
Menus	0.00						Owing	425.00
Address	Dublin Road Castletroy		Registered Office: Lee Duffy (Motors) Ltd					

Address Dún Da Road
Castletroy
Co. Limerick
Telephone 353 61 336000
Fax 353 61 330024
e-mail info@audilimerick.ie
Internet www.audilimerick.ie

Registered Office	Joe Duffy (Motors) Ltd Exit 5, M50 Northroad Dublin 11
Registered in VAT No.	Ireland 550383 3288047QH



Vehicle Health Check

WIP Number 46879

Customer Mr Jonathan O'Connor

Date 09/01/20

Follow Up Date

Phone Mobile: 0876335354

Vehicle A6 2.0TDI 190 S LINE S-T 20

Reg 182D6758

Kms

43777

Page: 1

INSTRUMENTS + CONTROLS	State	REPORT & RECOMMENDATIONS	PRICE (Inc. VAT)	STATUS
Check Horn	✓		0.00	
Check Wipers/Washers	✓		0.00	
Check Interior Lights/Controls	✓		0.00	
Check Dash Warnings	✓		0.00	
LIGHTS + LEVELS	State	REPORT & RECOMMENDATIONS	PRICE (Inc. VAT)	STATUS
Check Front Lights	✓		0.00	
Check Rear Lights	✓		0.00	
Check Oil Level Low?	✓		0.00	
Check Coolant Level	✓		0.00	
Check Brake Fluid Level	✓		0.00	
SERVICE ITEMS DUE	State	REPORT & RECOMMENDATIONS	PRICE (Inc. VAT)	STATUS
Oil Filter Due?	✓		0.00	
Pollen Filter Due?	✓		0.00	
Air Filter Due?	✓		0.00	
Fuel Filter Due?	✓		0.00	
Timing Belt Due?	✓		0.00	
Gear Oil Due?	✓		0.00	
Spark Plugs Due (Petrol only)?	✓		0.00	
NCT Due Date?	✓		0.00	
Add Blue Low Warning On Dash?	✓		0.00	
Fan Belt Condition?	✓		0.00	
Brake Fluid & Coolant Due?	✓		0.00	

NOTE: This report is the result of a visual examination only of those items listed. Further checks may be necessary to determine full extent of requirements.

Legend

- Requires urgent attention - Due for replacement immediately, is unsafe or may not last beyond 3 months*
- Advisory - Does not require immediate attention i.e. Does not require replacement within 3 months but may not last to next service*
- Visually OK - Estimated to make it to next service but advised to be checked between service intervals*

Based on current conditions and visual inspection*

THIS IS NOT AN INVOICE
(Prices are VAT inclusive and valid for 30days)

DISCLAIMER: Identified but unaddressed Red work or Warnings indicators (instrument cluster warning lights) may cause risk to your vehicle, yourself and other road users. By signing this document you are acknowledging that you understand your vehicles condition and its possible consequences if the vehicle is used in an unrepaired state on the public roads

Customer Signature:

DATA PROTECTION: The above named dealer or associated companies may wish to keep you informed about products, services and special offers. Please tick these boxes if the customer does not wish to receive further updates. By post ☐ By telephone ☐ By email ☐

Inspected by Signature:

E. & O. E.

© CDK Global

Address Dublin Road
Castletroy
Co. Limerick
Telephone 353 61 336000
Fax 353 61 330024
e-mail info@audilimerick.ie
Internet www.audilimerick.ie

Registered Office Joe Duffy (Motors) Ltd
Exit 5, M50
Northroad
Dublin 11
Ireland 550383
VAT No. 3288047QH



Complete record

Vehicle data

Vehicle identification number	WAUZZZ4G2JN100143
Type designation	A6 Sal. TDI2.0 I4140 A7
Date of delivery	2018-07-06

Inspection with oil change

Date	2020-01-09
Mileage/km	43777 km
Order number	46879
Additional work carried out	<input checked="" type="checkbox"/> Dust and pollen filter <input checked="" type="checkbox"/> Diesel fuel filter
Carried out by	Audi Limerick Castletroy, Dublin Road 00000 Limerick Ireland
Authorised Audi dealer	Yes
Mobility guarantee	Yes (until Service is displayed)

Inspection with oil change

Date	2018-11-27
Mileage/km	16765 km
Order number	37984
Additional work carried out	<input checked="" type="checkbox"/> Reducing agent
Carried out by	Audi Limerick Castletroy, Dublin Road 00000 Limerick Ireland
Authorised Audi dealer	Yes
Mobility guarantee	Yes (until Service is displayed)

Delivery inspection

Date	2018-07-03
Mileage/km	0 km
Order number	WAUZZZ4G2JN100143
Contract end	2021-07-03
Extended warranty	40000 km
NVO	



Complete record

Vehicle data

Vehicle identification number	WAUZZZ4G2JN100143		
Type designation	A6 Limo TDI2.0 R4140 A7		
Date of delivery	2018-07-06		
Extended warranty	Contract end	2021-07-05	
	Mileage/km	90000 km	

Inspection with Oil change (flexible)

Date	2021-08-21		
Mileage/km	74606 km		
Order number	60323		
Additional work carried out	✓ Dust and pollen filter		
	✓ Brake fluid service		
	✓ Gearbox oil		
	✓ Air cleaner element		
Carried out by	Audi Limerick		
	Castletroy, Dublin Road		
	00000 Limerick		
	Ireland		
Authorised Audi dealer	Yes		
Mobility guarantee	Yes (until Service is displayed)		

Inspection with oil change

Date	2020-01-09		
Mileage/km	43777 km		
Order number	46879		
Additional work carried out	✓ Dust and pollen filter		
	✓ Diesel fuel filter		
Carried out by	Audi Limerick		
	Castletroy, Dublin Road		
	00000 Limerick		
	Ireland		
Authorised Audi dealer	Yes		
Mobility guarantee	Yes (until Service is displayed)		

Audi
Service record



Inspection with oil change

Date	2018-11-27
Mileage/km	16765 km
Order number	37984
Additional work carried out	✓ Reducing agent
Carried out by	Audi Limerick Castletroy, Dublin Road 00000 Limerick Ireland
Authorised Audi dealer	Yes
Mobility guarantee	Yes (until Service is displayed)

Delivery inspection

Date	2018-07-03
Mileage/km	0 km
Order number	WAUZZZ4G2JN100143
Carried out by	NVD Balldonnell D22 Dublin Ireland
Authorised Audi dealer	Yes